

Incident Summary

Onaping Depth BEV Fire

2020-07-06



Description of Incident

Incident type:

- Fire of a battery electric vehicle (BEV) in an underground mine

Date/Time and Location:

- Glencore's Sudbury Integrated Nickel Operations, Onaping Depth Mine
- July 6, 2020 – Approximately 10:40pm.

Cause of Incident:

- Prior to the incident, battery fuses were mistakenly removed and replaced with shunts. The vehicle was operated with *no overcurrent protection* in place.
- The BEV's traction inverter failed resulting in a short circuit.
- The uninterrupted short circuit produced a tremendous amount of heat for a prolonged period. This subsequently ignited the battery and front tires, destroying the front half of the vehicle.

Description of Incident

Incident Summary

- On the evening of July 6th, two technicians were troubleshooting a battery electric vehicle (BEV) located on the 47- 4 level at Craig Mine in Onaping, Ontario.
- At approximately 10:40pm, while working on the unit a sudden high intensity electrical arcing event and fire took place.
- Technicians were trapped behind the burning truck, but for a period of time were able to communicate with first responders to initiate an emergency response.
- They located a functioning compressed air line and remained at the air header until the Mine Rescue team extinguished the fire.
- The technicians were then safely extracted to surface.



Figure 1 – BEV Fire

Description of Incident




Figure 2 – Post-Incident Photo of BEV



Incident Timeline

Incident Timeline

July to August 2017

- Vehicle was delivered to OEM's shop in Sudbury in mid-2017.
- Energy storage system consisted of three identical battery packs. Each pack was equipped with an internal fuse, as depicted in Figure 3.
- During an early vehicle inspection, Glencore noted the absence of an external means of achieving a zero-energy state during maintenance and requested that this feature be added.
- To address this, one manual service disconnect per battery pack with unfused modules (i.e. shunts) was installed (see Figures 4 and 5).
- Vehicle was put into service at Craig Mine in Sept 2017.




Figure 4 – Manual Service Disconnects




Figure 3 – Original Battery Fuse




Figure 5 – Unfused Module

Incident Timeline

November 2017 to January 2018

- Improper towing resulted in traction inverter damage and blown fuses. The inverter and original fuses needed to be replaced.
- Accessing the fuses required unmounting and disassembling each battery pack. It was noted that a module with an integrated fuse was available for the manual service disconnect which would make replacing fuses easier in the future.
- The following modifications to the design were made in conjunction with changes to the towing procedure:
 - Three 250A fused modules were used to replace the unfused modules (see Figure 5)
 - The original, internal fuses were eliminated.
- The removed unfused modules were kept in inventory.



Figure 6 – Fused Module

Incident Timeline

June to October 2019

- Another improper towing incident occurred damaging the traction inverter
 - Once again the inverter and fuses needed to be replaced
 - A further revision to the towing method and procedure was also made.
- Instead of the required 250A fused modules, the unfused modules that were previously removed were erroneously re-installed.
 - The fused and unfused modules are identical in appearance apart from the model number printed in small text (see figure 7).
- The vehicle was returned to service and operated with ***no overcurrent protection in place*** for the main battery and traction inverter.




Figure 7 – Comparison of Modules

Incident Timeline

July 6, 2020

- The inverter failed while OEM technicians were troubleshooting. With no overcurrent protection in place, a severe and uncontrolled electrical fault occurred.
- The investigation found unfused modules installed instead of the correct fused modules (see figure 8 and 9 comparing as found to new).



Figure 8 – Unfused Module (Internal)




Figure 9 – Manual Service Disconnects – Before and After Incident

Incident Timeline

July 6, 2020

- The traction inverter was totally destroyed as a result of the failure.
- The failed inverter was further disassembled which revealed a significant portion of the traction inverter copper bus melted away (see figure 10).
- This is clear evidence of a prolonged and uncontrolled electrical fault that originated in the traction inverter which generated a tremendous amount of heat.





Figure 10 – Internal DC Bus Bar extracted from Failed Traction Inverter

Incident Timeline

- Figure 11 is a set of simplified battery pack schematics depicting the modifications that took place over the life of the battery electric vehicle leading up to the fire



1) Original design was fused, but did not include an external disconnecting means to achieve zero energy.

2) Unfused service disconnect module was added to satisfy the need to achieve zero energy during servicing.

3) Unfused service disconnect was replaced with a fused version. This eliminated the need for an internal fuse.

4) Fused service disconnect was accidentally replaced with an unfused version. No overcurrent protection is present.

Figure 11 – Simplified Schematics depicting modifications to fuse arrangement.



Incident Discussion

Preventions and Mitigations

Incident Discussion

Preventions & Mitigations

- The following slides present ideas and suggestions for preventing such an incident in the future.

Incident Discussion

Preventions & Mitigations

Overcurrent Protection

- Overcurrent protection on BEVs is critical!
 - Give robust coverage / consideration of this topic in BEV specifications.
 - OEMs should provide clarity and transparency on this topic.
 - Purchasers of BEVs should have a clear understanding of the overcurrent protection scheme being employed.

Incident Discussion

Preventions & Mitigations

Overcurrent Protection

- Combination disconnect/fuse modules, like the one depicted in Figure 12, can be convenient. But perhaps they are **too** convenient.
 - Anyone can remove/change the module.
 - Easy to change fuse ratings, or as in this incident, eliminate the fuse altogether.
 - Not clearly/boldly marked as to what it is (rating, etc.)
 - Dual purpose – fuse *and* isolation means. This may not be a good thing.
 - If the main battery fuse does blow, should it be really easy to replace?



Figure 12 – Service Isolation Device

Incident Discussion

Preventions & Mitigations

Overcurrent Protection (continued)

- Consider specifying that Main fuses/overcurrent protection require a tool to remove or replace. This may help ensure that only authorized persons perform this task.
 - Battery fuses in particular should *never* blow unless a severe fault has occurred. It should not be a “routine” task to replace these – qualified person should be involved.
 - Still need to make sure it is safe for the person to remove/replace the fuses.
- Should ensure that labels are present, indicating make/model/rating of each overcurrent device. This way, it is clear to maintenance personnel what *should* be installed.
- Also need to ensure that the overcurrent protection devices themselves are well marked and easy to identify.
 - A fuse should *look* like a fuse. A circuit breaker should *look* like a circuit breaker. And a copper shunt should *look* like a copper shunt.



Figure 13 – Example of Fuse for EV Use

Incident Discussion

Preventions & Mitigations

Overcurrent Protection (continued)

- Give consideration to redundancy where overcurrent protection is concerned. On this vehicle, the main battery fuses were the *only* overcurrent protection in place between the batteries and the traction inverter.
 - If there had been a set of dedicated, properly rated inverter fuses, this incident would have been prevented – even in the absence of the main battery fuses.
 - At least two layers of overcurrent protection is advisable. This provides a layer of redundancy, and also could help with protection co-ordination.
- Finally, make sure the overcurrent protection is in place:
 - Carefully review the design during the engineering process.
 - Include overcurrent protection checks on commissioning checklists.
 - If the vehicle undergoes an overhaul or major repair, be sure to re-commission / re-check the overcurrent protection.
 - Check for the presence and condition of overcurrent protection during routine maintenance, at appropriate intervals.

Incident Discussion

Preventions & Mitigations

Towing

- The inverter failure was a result of towing the vehicle with the motor still coupled to the inverter.
 - Many vehicles use permanent magnet traction motors. These will generate a voltage when the rotor is turned.
 - This voltage can cause damage to the inverter.
- Give careful consideration to how a vehicle might be towed
 - OEMs should make the towing procedure as simple and straightforward as possible.
 - Operators of BEVs should understand the towing procedures.
- Ideally, the BEV should automatically switch to a “towing friendly” mode anytime it is not driving. The only operator action to initiate towing should be to disengage the brakes.



Additional Thoughts

Additional Thoughts

Electrical Design / Arc Flash

- Need for transparency with respect to electrical design.
- Modelling of the electrical system
 - Single Line Diagram (SLD) of overall system is a must!
 - Available short circuit current from the battery system.
 - Are protective/control devices (fuses, circuit breakers, contactors..) appropriate for application?
 - Protection co-ordination / TCC curves
- Arc Flash Analysis - Challenging with DC systems - Dependent on:
 - Number + Capacity of batteries
 - Battery internal resistance / Available Fault Current
 - Selection and arrangement of Fuses




Figure 14 – Example of Electrical Single Line / Model

Additional Thoughts

Transportation and Testing

- Li-Ion Batteries fall under Transportation of Dangerous Goods Regulations
 - Classified under UN3480.
 - Testing according to UN “Manual of Tests and Criteria” section 38.3.
- In addition, many other safety testing regimens
 - UL 2580 – Batteries for Use In Electric Vehicles
 - UNECE 100
 - SAE J2464, J2929



Addendum 99: Regulation No. 100



UNITED NATIONS

SAE
J2929

Additional Thoughts

Electrical / Battery Design Aspects

- Design to minimize likelihood of propagation
 - Modularized battery system, with thermal breaks
 - Selection of battery chemistry / configuration
 - Isolate / separate contactors, circuit breakers, etc... from batteries/cells.
- Monitoring / Troubleshooting of battery, drivetrain & electrical system
 - Robust BMS system – monitor battery parameters.
 - “Software” overcurrent / power flow monitoring
 - Fault Codes – Telemetry, remote support and strong documentation for troubleshooting



Thank You!
Questions?